

R 280635Z AUG 00 PSN 400759T25
 FM USS HAWES
 TO AIC CATIS NORFOLK VA/D13/
 INFO CINCUSNAVEUR LONDON UK//N2/N3/N5//
 COMUSNAVCENT
 COMFIFTHFLT//N2/N3/N5//
 USTRANSCOM SCOTT AFB IL//TCJ-2//
 JAC MOLESWORTH RAF MOLESWORTH UK//DAO//
 COMNAVSURFLANT NORFOLK VA//N2/N3//
 COMGWBATGRU
 CTF FIVE ZERO
 COMSUBRON TWO TWO
 COMSUBRON TWO TWO
 NAVCRIMINSERVFO EUR NAPLES IT//EUNA//
 COMDESRON TWO TWO
 BT
 UNCLAS //N03510//
 EXER///
 MSGID/GENADMIN/HAWES//
 SUBJ/NIIP PROGRAM FORMATTED LESSONS LEARNED SUBMISSION
 FOR ADEN, YEMEN//
 REF/A/DOC/C6F/5000.1M/970312/-/-//
 AMPN/C6F DEPLOYMENT DIRECTIVES MANUAL//
 RMKS/DATA FORMATTED FOR PROCESSING BY NIIP SOFTWARE.//
 CAPSCHECK/F//
 IIPID/51786-86876/U/-/-/-//
 CLASDAT/-/-//
 TITLE/PORT VISIT REPORT TO ADEN, YEMEN//
 OPEXCMD/-/FFG 53//
 LLPOC/LT [REDACTED]/564-6619/(757)444-6619//
 OBSTXT/U/-/-/1. PORT VISIT SUMMARY. //
 ///
 / A. NAME OF PORT: ADEN, YEMEN//
 ///
 / B. GEOGRAPHIC LOCATION: 1247N4-04457E0//
 ///
 / C. NAME OF VESSEL: USS HAWES (FFG 53)//
 ///
 / D. NAME OF COMMANDING OFFICER: CDR [REDACTED]//
 ///
 / E. DATE OF VISIT: 21 AUG 00//
 ///
 / F. TIME ZONE: -3C//
 ///
 /2. NAVIGATIONAL INFORMATION.//
 ///
 A. DESCRIPTION OF PORT: ADEN HARBOR IS A FINE NATURAL HARBOR
 /ENTERED BETWEEN ADAN AS SUGHRA AND ADEN PENINSULA. THE PORT
 /CONSISTS OF AN OUTER HARBOR AND INNER HARBOR. IT IS A
 /TRANSSHIPMENT PORT AND AN IMPORTANT FUELING STATION. IT AFFORDS
 /SHELTER FROM ALL DIRECTIONS EXCEPT FROM THE SOUTH. THE INNER
 /HARBOR IS PARTIALLY PROTECTED FROM THE SW BY A BREAKWATER.//
 ///
 / B. APPROACHES, LIGHTS, ETC.: THE BUOY CHANNEL CAN BE EASILY
 /DISTINGUISHED BY THE BUOY PATTERN. THE BUOYS ARE WELL LIT AND
 /MARK THE CHANNEL WELL.//
 ///
 / C. PILOTAGE: PILOTAGE IS COMPULSORY.//
 ///
 / D. ENTRANCE: NC//
 ///
 / E. CHANNEL: HAWES USED CHARTS 62097 AND 62098. DEPTHS AND
 /NAVAIDS ARE RELIABLE. HAWES NOTED AND PILOT CONFIRMED THAT THE

Encl (52)
Page 1 of 3

/RANGE ON THE 047 LEG INBOUND DOES NOT LINE UP WITH THE CHANNEL.
/RECOMMEND IGNORING THE RANGE. PILOT OFFERED GOOD ADVISE AND
/CHANNEL ON CHART APPEARED TO BE ACCURATE.//

///

/ F. ANCHORAGES: ANCHORAGE AREA WAS CROWDED WITH MERCHANT
/VESSELS.//

///

/ G. WRECKS AND OBSTRUCTIONS: NC//

///

/ H. TIDES AND CURRENTS: TIDAL RANGE WAS APPROX 3 FT AND TIDAL
/CURRENT WAS APPROX 1.5 KTS.//

///

/ I. WEATHER AND WINDS: STRONG WINDS FROM THE N TO NW CAN
/PRODUCE SANDSTORMS, WHICH ARE ESPECIALLY PREVALENT AROUND SUNSET
/IN THE MONTHS OF MAY TO AUGUST.//

DISTXT/U/-/-/3. BERTHING AND FACILITIES.//

///

/ A. MOORINGS, DOCKS, ETC.: HAWES MOORED TO MOORING DOLPHIN 7.
/LOGREQ RESPONSE STATED HAWES WOULD BE GOING TO "THE MOORING
/DOLPHIN". THIS WAS VAGUE AND HAWES HAD TO CONFIRM WITH ADEN
/PORT CONTROL, VIA BTB, WHICH MOORING DOLPHIN WAS ASSIGNED.
/MOORING DOLPHIN 7 IS LOCATED AT 12-47'57"N AND 044-58'54"E.//

///

/ B. FUEL, LUBE AND DIESEL OIL: HIGH QUALITY F76 AND JP5 TAKEN.
/ F76 HOSE WAS POOR QUALITY, SUSCEPTIBLE TO CHAFFING. PUMP RATE
/FOR JP5 WAS SLOW, APPROX 75 GPM. THREADED TO FLANGE ADAPTOR IS
/REQUIRED FOR JP5. VARIOUS SIZE FLANGES AVAILABLE FOR
/CONNECTION.//

///

/ C. MECHANICAL HANDLING FACILITIES: NC//

///

/ D. DRYDOCKS AND REPAIR FACILITIES: NC//

///

/ E. WAREHOUSE AND STORAGE FACILITIES: NC//

///

/ F. STEVEDORES: NC//

///

/ G. PORT CAPACITY: NC//

///

/ H. ROAD, RAIL AND STEAMER TRANSPORTATION: NC//

LLTXT/U/-/-/4. SERVICES, LOGISTICS AND OPERATIONS.//

///

/ A. LIGHTERAGE: NC//

///

/ B. DREDGES AND MISCELLANEOUS CRAFT: NC//

///

/ C. WATER: NO WATER WAS TAKEN. CHT WAS DISCHARGED TO A BARGE.//

///

/ D. AIRFIELDS: NC//

///

/ E. COMMUNICATIONS: NO PHONES LINES AVAILABLE AT MOORING
/DOLPHIN 7.//

///

/ F. MEDICAL: NC//

///

/ G. GASOLINE: NC//

///

/ H. PROVISIONS: HUSBANDING AGENT PROVIDED GREAT SUPPORT.
/RECOMMEND WASHING FFV WITH HIGHER CONTENT OF CHLORINE AND WASH
/MORE CAREFULLY. HIGHER CONTENT OF INSECTS IN FFV.//

///

/ I. GARBAGE DISPOSAL: GARBAGE DISPOSED OF VIA BARGE.//

PECTXT/U/-/-/5. PERSONALIA.//

///

Encl (52)
Page 2 of 3

/ A. CALLS: NTR//
///
/ B. HONORS: REQUIRED TO FLY A YEMEN FLAG WHILE INPORT.
/HUSBANDING AGENT PROVIDED FLAG UPON ARRIVAL.//
///
/6. PORT VISIT INFORMATION.//
///
/ A. GENERAL INFORMATION: NTR//
///
/ B. LIBERTY: LIBERTY WAS NOT GRANTED. HAWES WAS INPORT FOR
/BSF.//
///
/ C. CLUBS AND BARS: NTR//
///
/ D. RESTAURANTS: NTR//
///
/ E. HOTELS: NTR//
///
/ F. ATHLETICS: NTR//
///
/ G. BEACHES: NTR//
///
/ H. CHURCHES: NTR//
///
/ I. TRANSPORTATION: NTR//
///
/ J. TOURS: NTR//
///
/ K. SHOPPING: NTR//
///
/ L. THEATER AND MOVIES: NTR//
///
/ M. PHYSICAL SECURITY: NTR//
///
/ N. MISCELLANEOUS INFORMATION: NTR//
BT

Encl (52)
Page 3 of 3