

No. A- 3000

AIRCRAFT RECORD

Des. No. A-3000

Contract No. 36228 Req. CR 380

S. E.

Bu- 18

Cost Price
Flat Price

Contractor B. F. Goodrich Co.,

Address Akron, O.

Model Capnot "R" Type

Kite Balloon

Motor H. P.

Inspector Hood

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air	Date	Wire	S. Order	Shipped	Destination	Received
				10/24/18	B. Admiralty	
	2-17-19					
	1-5-39			2-28-19	Gloucester	Drawn and 4-1-19
	3-15-20				Quarterly Report 4/14/22 Naval Supply	
	165			3-22-20	Hampton Roads Station	4-8-20

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Sold Let. NOB. H Roads 10-1-23
161-0

Total Flying Time Hours Minutes Stricken from Navy List

Des. No. A-

3001

AIRCRAFT RECORD

Des. No. A-

Contract No.

36228

Req.

CR 380

S. E.

Bu- 18

Cost Price
Flat Price

Contractor

B. F. Goodrich Co.,

Address Akroq, O.

Model

Gaquot "R"

Type

Kite Balloon

Motor

H. P.

Inspector

Hood

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% + 100%

F. O. B.

Accepted

Op. Air

Date

Wire

S. Order

Shipped

Destination

Received

10/24/18 B- Admiralty
2-17-19 1539 2-28-19 Gloucester
7-30-19 2632 8-5-19 San Diego
3/15/20 4-2-20 Pacific Fleet

Draw Card
4-1-19

4-2-20

Op. let. 3/130-A-5, Op. 29B-HA

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

7-26-21

8-16-19

2

TROUBLE REPORTS

Date

Station

Remarks

4-4198

7-8-21 San Diego

Deterioration of fabric. Due to age, etc.
Recommended that balloon be stricken.

Jes. No. A-

3002

AIRCRAFT RECORD

Des. No. A- 3002

Contract No. 36228 Req. CR 380 S. E.

Bu- 18

Cost Price
Flat Price

Contractor B. F. Goodrich Co.,

Address Akron, O.

Model Caqnot "R" Type Kite Balloon

Motor H. P.

Inspector Hood

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination Received

				10/24/18	B. Admiralty		
2-17-19				2-28-19	Gloucester		Drawn and 4-1-19
1539					Quarterly report 4/3/22	Naval Supply	
3-15-20				3-22-20	Hampton Roads	Station	4-8-20
165							

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Sold Let 70 B-14 Roads 10-1-23
161-0

Total Flying Time Hours Minutes Stricken from Navy List

Des. No. A-

3003

AIRCRAFT RECORD

Des. No. A-300

Contract No. 36228

Req. CR 380 S. E.

Bu- 18

Cost Price
Flat Price

Contractor B. F. Woodrich Co.,

Address Akron, O.

Model Canot "R" Type Kite Balloon

Motor H. P. Inspector Hood

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air	Date	Wire	S. Order	Shipped	Destination	Received
				10/24/18	B. Admiralty	
	2-17-19		1539	2-28-19	Gloucester	Drum Ser 4-1-19
	3-15-20		164	3-31-20	N. A. F.	about 4-4-20
			265	4-8-20	Pensacola	4-26-20

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

5/8/22

2

TROUBLE REPORTS

Date

Station

Remarks

4-4198

2/29/22 Pensacola Survey Report - Fabric deteriorated and torn. Unserviceable. Stricken - Sec Nav. let 5/8/22

Des. No. A- 3004

AIRCRAFT RECORD

Des. No. A- 2

Contract No. 36228

Req. CR 380 S. E.

Bu- 18

Cost Price
Flat Price

Contractor B. F. Woodrich Co.,

Address Akron, O.

Model Canot "R" Type Kite Balloon

Motor H. P.

Inspector Hood

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Op. Air	Date	Wire	S. Order	Shipped	Destination	Accepted	Received
				10/24/18	B. Admiralty		
			2-17-19	2-28-19	Gloucester		cran Serd 4-1-19
			1539	8-5-19	San Diego		
			7-30-19	4-2-20	Pacific Fleet		4-2-20
			2632				

Spa. det. 3/30-A-5, Op. 29 B-HA.

3/15/20

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

7-26-21

(8-4-1921)

2

TROUBLE REPORTS

4-4198

Date	Station	Remarks
7/16/20	San Diego, Calif.	A-3004. Diffusion due to deterioration of fabric. Recommended that it be stricken from the Navy list.
7-8-21	San Diego	Diffusion Diffusion due to deterioration. Recommended that plane be stricken.

Des. No. A-

3005

AIRCRAFT RECORD

Des. No. A- *2*

Cost Price
Flat Price

Contract No. 36228 Req. CR 380

S. E.

Bu- 18

Contractor B. F. Goodrich Co.,

Address Akron, O.

Model Cagnot "R" Type Kite Balloon

Motor II. P.

Inspector Hood

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Oct . Accepted

Op. Air	Date	Wire	S. Order	Shipped	Destination	Received
	10-17-18					
	554					
				<i>10/12/18</i>	<i>Brooklyn, British</i>	
				<i>10-28-18</i>	<i>Gloucester, Eng.</i>	
					<i>Sold to British Admiralty</i>	

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time	Hours	Minutes	Stricken from Navy List
			<i>6/9/20</i>

Des. No. A-

3006

AIRCRAFT RECORD

Des. No. A-31

Contract No. 36228

Req. CR 380 S. E.

Bu- 18

Cost Price
Flat Price

Contractor B. F. Goodrich Co.,

Address Akron, O.

Model Capnot "R" Type Kite Balloon

Motor H. P.

Inspector Hood

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Op. Air	Date	Wire	S. Order	Shipped	Destination	Accepted	Received
						<i>Oct.</i>	
	10-17-18	2-17-19			<i>10/12/18 Brooklyn, British</i>		
	<i>554</i>	1539		<i>10-28-18</i>	<i>Gloucester (Earls Court) Eng.</i>		
					<i>Sold to British Admiralty</i>		

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

6/9/20

Des. No. A- 3007

AIRCRAFT RECORD

Des. No. A- 3

Contract No. 36228

Req. C.R 380 S. E.

Bu- 18

Cost Price
Flat Price

Contractor B. F. Goodrich Co.,

Address Akron, O.

Model Cagnot "R"

Type Kite Balloon

Motor

H. P.

Inspector

Hood

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Op. Air	Date	Wire	S. Order	Shipped	Destination	Accepted	Received
						<i>Oct.</i>	
	<i>10-17-18</i>	<i>554</i>	<i>2-17-17</i>	<i>10-12-18</i>	<i>Brooklyn, N.Y.</i>		
			<i>10-28-18</i>		<i>Gloucester, England</i>		
					<i>Sold to British Admiralty</i>		

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

6/9/20

Des. No. A-

3008

AIRCRAFT RECORD

Des. No. A-3008

Contract No. 36228

Req. CR 380

S. E.

Bu-18

Cost Price
Flat Price

Contractor E. F. Goodrich Co.,

Address Akron, O.

Model Capnot "R"

Type

Kite Balloon

Motor

H. P.

Inspector

Hood

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Op. Air Date Wire S. Order Shipped Destination Received

Oct Accepted

				10/19/18	B. Admiralty		
	2-17-19			2-28-19	Gloucester		Oran Sound 4-1-19
	15-39			3-27-20	Hampton Roads Station	Naval Supply	4-8-20
	3-15-20			4/25/23	Lakehurst	M. R. 5731/23	5/4/23
	165						
	3-2-15						
	4/17/23						

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Stricken Let See navy aer. m. 22 RFL 1-12 4-23-24

Total Flying Time

Hours

Minutes

Stricken from Navy List

4/23/24

2

TROUBLE REPORTS

Date

Station

Remarks

4-4198

3-17-24

Lakehurst-

Q. 3008 Ripped on field Sept. 6-23 - fabric found to be deteriorated. Empenage split due to age. Reggine salvaged for general use, Envelopes cut up for tarpaulins.

Des. No. A-

3009

AIRCRAFT RECORD

Des. No. A-

Contract No. 36228

Req. CR 380 S. E.

Bu- 18

Cost Price
Flat Price

Contractor B. F. Woodrich Co.,

Address Akron, O.

Model Caqnot "R" Type Kite Balloon

Motor H. P.

Inspector Hood

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Op. Air	Date	Wire	S. Order	Shipped	Destination	Accepted	Received
						<i>Out.</i>	

10-17-18 ~~*17-19*~~
554 ~~*1539*~~ *10-28-18* *Brooklyn* *British*
Gloucester *Pauls Court, Eng.*
Sold to British Admiralty

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

6/9/20

Des. No. A-

3010

AIRCRAFT RECORD

Des. No. A-⁵

Contract No.

36228

Req. CR 380

S. E.

Bu-18

Cost Price
Flat Price

Contractor

B. F. Goodrich Co.,

Address

Akron, O.

Model Cagnot "R"

Type

Kite Balloon

Motor

H. P.

Inspector

Hood

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Op. Air

Date

Wire

S. Order

Shipped

Destination

Oct. Accepted

Received

~~10-17-18~~
554

10/12/18 *Brooklyn, British*
10-28-18 *Gloucester, Eng.*

Sold to British Admiralty

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

6/9/20

4-4198

Des. No. A- 3011

AIRCRAFT RECORD

Des. No. A- 2

Contract No. 36228

Req. CR 380

S. E.

Bu- 18

Cost Price
Flat Price

Contractor B. F. Goodrich Co.,

Address Akron, O.

Model Canot "R" M Type

Kite Balloon

Motor H. P.

Inspector Hood

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F.O.B.

Op. Air	Date	Wire	S. Order	Shipped	Destination	Accepted	Received
						<i>No</i>	

Lost during trials

*10-24-19
2938 11-6-19 San Diego (Envelope only)*

Accessories Lacking at Shipment Bureau Advised Accessories Supplied

Total Flying Time Hours Minutes Stricken from Navy List *9/9/19*

2

TROUBLE REPORTS

4-4198

Date	Station	Remarks
July 1919	<i>See Bu C + R let, C-36222 of 6-25-19 and resulting Trouble Report.</i>	In need of repair. Recommended to be stricken from list.

Des. No. A- 3012

AIRCRAFT RECORD

Des. No. A- 6

Contract No. 36228 Req. CR 380

S. E.

Bu- 18

Cost Price
Flat Price

Contractor E. F. Goodrich Co.,

Address Akron, O.

Model Cagnot "X" Type

Kite Balloon

Motor H. P.

Inspector Hood

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Op. Air Date Wire S. Order

Shipped

Hood

Destination

Jan

Accepted

Received

*Hampton Pds
W.S. Shawmont
H. P. ...*

Feb.

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

8-14-20

2

TROUBLE REPORTS

Date

Station

Remarks

4-4198

7/30/20 Hampton Roads

Balloon unfit for further service. Fabric worn and mildewed. It is recommended that A-3012 be stricken from the Navy list.

Des. No. A-

3013

AIRCRAFT RECORD

Des. No. A-2

Contract No. 36228

Req. CR380

S. E.

Bu- 18

Cost Price
Flat Price

Contractor E.F. Goodrich Co.,

Address Akron, O.

Model Cagnot "R" m Type

Kite Balloon

Motor H. P.

Inspector Hood

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Op. Air Date Wire S. Order Shipped

Destination

Accepted

Received

Jan
Hampton Roads U.S. Naval Air Station
Hampton Roads

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

8-14-20

4-4198

TROUBLE REPORTS

2
Date

Station

Remarks

4-4198

7/30/20 Hampton Roads

Balloon unfit for further service. Fabric worn out because of bad weather conditions. It is recommended that A-3013 be stricken from the Navy list.

Des. No. A- 3014

AIRCRAFT RECORD

Des. No. A-c

Contract No. 36228 Req. CR 380 S. E.

Bu- 18

Cost Price
Flat Price

Contractor B.F. Goodrich Co.

Address Akron, O.

Model Caqnot ~~X~~" 7" Type Kite Balloon

Motor H. P.

Inspector Hood

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

Op. Air Date *Nov.* Wire S. Order

Shipped

Jan
Destination

Accepted

Received

*Hampton Roads
Shawmut*

Feb.

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

7-8-19

2
TROUBLE REPORTS

Date

Station

Remarks

4-4198

4/6/19

Kite Balloon damaged. Completely beyond repair
and it is recommended to be ~~stricken~~ stricken from list.

Des. No. A- 3015

AIRCRAFT RECORD

Des. No. A- 30

Contract No. 36228 Req. CR 380 S. E.

Bu- 18

Cost Price
Flat Price

Contractor E.F. Goodrich Co.,

Address Akron, O.

Model Caqnot "R" m Type Kite Balloon,

Motor H. P.

Inspector Hood

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Op. Air	Date	Wire	S. Order	Shipped	Destination	Accepted	Received
		<i>hood</i>		<i>Jan</i>		<i>Feb.</i>	

3-11-19 San Diego
Op. letter 3/30-A-5-Op. 29 B-HA, 3/15/20 H-2-20 Pacific Fleet
H-2-20

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time Hours Minutes Stricken from Navy List

2/15/20

Des. No. A- 3016

AIRCRAFT RECORD

Des. No. A-

Contract No. 36228 Req. CR 380 S. E.

Bu- 18

Cost Price
Flat Price

Contractor B.F. Goodrich Co.,

Address Akron, O.

Model Caqnot "X" 27 Type Kite Balloon,

Motor II. P.

Inspector Hood

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Op. Air	Date	Wire	S. Order	Shipped	Destination	Received
	<i>Nov</i>			<i>Jan</i>	<i>Del.</i>	Accepted

3-11-19 San Diego
4-2-20 Pacific Fleet
4-2-20

to let. 3/30-A-5, Op. 29B-HA, 3/15/20

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time Hours Minutes Stricken from Navy List *2-28-21*

2
TROUBLE REPORTS

Date

Station

Remarks

4-4198

2/11/21

Pacific Flt.

Worn out in use. Continuous employment.
Recommended that this balloon be stricken
from the list.

Des. No. A-

3017

AIRCRAFT RECORD

Des. No. A-

Contract No.

36228

Req. CR 380

S. E.

Bu- 18

Cost Price
Flat Price

Contractor

E. F. Goodrich Co.,

Address

Akron, O.

Model Cagnot

"X" m

Type

Kite Balloon

Motor

H. P.

Inspector

Hood

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100%

F. O. B.

Op. Air

Nov.

Date

Wire

S. Order

Shipped

Jaw

Destination

Jkt

Accepted

Received

Sp. let. 3/30-A-5, Op. 29B-HA, 3/15/20

*3-11-19 San Diego
4-2-20 Pacific Fleet*

4-2-20

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time

Hours

Minutes

Stricken from Navy List

6/18/20

(10-25-87)⁴¹⁹⁸

2

TROUBLE REPORTS

4-4198

Date	Station	Remarks
5/21/20	San Pedro, Cal. (Pacific Fleet)	Kite balloon A-3017 was struck by lightning and burned. Machine is total loss. It is recommended that this balloon be stricken from the Navy list and accessories be used as spare parts.

No. A-

3018

AIRCRAFT RECORD

Des. No. A- 301

Contract No. 36228 Req. CR 380 S. E.

Bu- 18

Cost Price
Flat Price

Contractor B.F. Goodrich Co.,

Address Akron, O.

Model Capnot *Q*"m Type Kite Balloon

Motor H. P. Inspector Hood

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Op. Air	Date	Wire	S. Order	Shipped	Destination	Accepted	Received
	<i>Nov</i>				<i>Del.</i>	<i>Del.</i>	<i>Complete</i>

5-23-19
2241
S.O. 2774
5-25-19

5/28/19
9-19-19

*Command Akron of air 4-12-19
Marginal Parkway, Brooklyn
Hampton Roads*

10-15-19

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

*Sold Lit No B - H. Prads 10-1-23
161-0*

Total Flying Time

Hours

Minutes

Stricken from Navy List

4-4199

Des. No. A- 3019

AIRCRAFT RECORD

Des. No. A- *4*

Contract No. 36228 Reg. CR 380 S. E. Bu- 18
 Contractor E.F. Goodrich Co., Address Akron, O.
 Model Gagnot "X" Type Kite Balloon
 Motor II. P. Inspector Hood

Cost Price
Flat Price

PRODUCTION RECORD

10%	20%	30%	40%	50%	60%	65%	70%	75%	80%	85%	90%	95%	100%	F. O. B.
	<i>Nov</i>						<i>Feb.</i>						<i>March</i>	Accepted
Op. Air	Date	Wire	S. Order	Shipped	Destination	Received								

5-23-19
8-24-19
~~*8-25-19*~~
5/28/19 Marginal Parkway, Brooklyn
9-19-19 Hampton Roads
 Naval Supply Station, Hampton (for U. S. S. Penna)
 Accessories Lacking at Shipment Bureau Advised Accessories Supplied
4-12-19
120-2-334
10-15-19

See Navy let. Aer. M-24-CSE
6-12-19
6-85

Total Flying Time Hours Minutes Stricken from Navy List *8/2/22* 4-4198

2

TROUBLE REPORTS

Date	Station	Remarks	4-4198
6/12/22	Quantico Va	A-3019 This balloon was received at this station Nov. 23 - 1921 - from H. Roads Va - On inspection it was found the fabric was rotten, deteriorated to such an extent that the Surveying officer deemed it unsafe to inflate & sent up on another flight. Recommended this balloon be destroyed as unsafe & dropped from the returns of the Accountable Officer.	

Des. No. A-

3020

AIRCRAFT RECORD

Des. No. A-3020

Contract No. 36228 Req. CR.380 S. E. Bu- 18 Cost Price Flat Price

Contractor B. F. Goodrich Co., Address Akron, O.

Model Caquot ~~11m~~ Type Kite BalloonMotor ~~RM~~ H. P. Inspector Hood

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F.O.B.

Op. Air	Date	Wire	S. Order	Shipped	Destination	Accepted	Received
	Nov.				Det.	Det. March	

5-23-19
~~2-24-19~~
~~8-31-19~~
~~8-25-19~~

5/28/19
 9-19-19

4-12-19
 4-22-19
 Copeman at Akron
 Marginal Parkway, Brooklyn
 Huntington Beach

10-15-19

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

(In R. Spt. -22 - in storage)

2468

Stricken Let See Navy Aer. M. 43-REM-A4-1
 Lakehurst
 Naval Supply Station, Hampton (for U.S.S. Benma.)

Total Flying Time

Hours

Minutes

Stricken from Navy List

3-31-80

4-4198

2

TROUBLE REPORTS

4-4198

Date

Station

Remarks

3-11-30

Lakehurst - Survey 26-B-30

Des. No. A-3021-3204, incl. AIRCRAFT RECORD

Des. No. A-

Cost Price
Flat Price

Contract No.	Req.	S. E.	Bu-
Contractor			Address
Model	Type		
Motor	H. P.		Inspector

PRODUCTION RECORD

10%	20%	30%	40%	50%	60%	65%	70%	75%	80%	85%	90%	95%	100%	F. O. B.	
Op. Air	Date	Wire	S. Order	Shipped										Accepted	Received

Continued

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

Total Flying Time	Hours	Minutes	Stricken from Navy List
-------------------	-------	---------	-------------------------

No. A- 3028

AIRCRAFT RECORD

Des. No. A-

Contract No.

Req.

S. E.

Bu-

Cost Price
Flat Price

Contractor

Address

Model

Type

Motor

H. P.

Inspector

PRODUCTION RECORD

10% 20% 30% 40% 50% 60% 65% 70% 75% 80% 85% 90% 95% 100% F. O. B.

Accepted

Op. Air Date Wire S. Order Shipped Destination

Received

*Reports this Balloon sold by an 8695-
cat-- 221-BQ Lot no 11.*

NSS N.O B H Roads

Accessories Lacking at Shipment

Bureau Advised

Accessories Supplied

*According to the Bu records
was cancelled.*

3021-3201 incl

Let H.R. 10-16-23 — 161-0

Total Flying Time

Hours

Minutes

Stricken from Navy List

A3021 - A3099

CANCELLED
